ONEIDA NURSING CENTE PAGE 08/10 4232869142 12/18/2010 05:25 PRINTED: 12/06/2010 FORM APPROVED DEPARTMENT OF HEALTH AND HUMAN SERVICES OMB NO. 0938-0391 CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: AND PLAN OF CORRECTION A. BUILDING 01 - MAIN BUILDING 01 B. WING 12/05/2010 445254 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 18805 ALBERTA DR ONEIDA NURSING AND REHAB CENTER ONEIDA, TN 37841 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION SUMMARY STATEMENT OF DEFICIENCIES (EACH CORRECTIVE ACTION SHOULD BE (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) K 000 K 000 INITIAL COMMENTS 42 CFR 483.70(a) K3 BUILDING: 1-story Type II(222), unprotected, non-combustible construction with a complete automatic sprinkler system. K6 PLAN APPROVAL: 1965 K7 SURVEY UNDER: 2000 EXISTING K8 56-bed SNF/NF 12/10/10 K 045 Additional two bulbs fixtures NFPA 101 LIFE SAFETY CODE STANDARD K 045 were added at exit discharge of SS=E 400 & 500 hall. Light fixtures Illumination of means of egress, including exit discharge, is arranged so that failure of any single were connected to generator to lighting fixture (bulb) will not leave the area in provide continuous illumination darkness. (This does not refer to emergency during any power interruption. lighting in accordance with section 7.8.) 2 Environmental Services will 1.

This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to assure exit discharge for two (2) of five (5) exits were lighted so the failure of any single

The findings include:

darkness (NFPA 101, 7.8.1.4)..

Observation and interview with the Maintenance Supervisor, on December 5, 2010 at 10:30 a.m. confirmed the outside lights at the end of two (2) resident halls exiting the building were single bulb fixtures.

lighting fixture (bulb) would not leave the area in

NFPA 101 LIFE SAFETY CODE STANDARD K 144

SS=F Generators are inspected weekly and exercised under load for 30 minutes per month in accordance with NFPA 99. 3.4.4.1.

Monitor fixtures weekly x 3 months and then periodically.

3 Environmental Services will report to the Quality Assurance Committee monthly for compliance-The Quality Assurance Committee members are The Medical Director, Administrator, Director of Nursing, Asst. Director of Nursing, Social Services, Rehab Services, Medical Records, Dietary Manager, Minimum Data Set Nurse, Environmental Supervisor, and Maintenance Director.

K 144 1 On December 14, we began seeking bids for the installation of an annunicator panel to the generator.

2 Once we receive two (2) adequate quotes for the installation of the annunciator panel,

LABORATORY DIRECTOR'S OR PROVIDER SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE .

(X5) DATE

1/21/11

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is regulate to continued program participation.

PAGE 09/10

PRINTED: 12/06/2010 FORM APPROVED

DEPARTMENT OF HEALTH AND HUMAN SERVICES

OMB NO. 0938-0391 CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: 01 - MAIN BUILDING 01 A. BUILDING B. WING_ 12/05/2010 445254 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 18805 ALBERTA DR ONEIDA NURSING AND REHAB CENTER ONEIDA, TN 37841 (X5) COMPLETION DATE PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE (X4) ID PREFIX CROSS-REFERENCED TO THE APPROPRIATE PRÉFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) 2 cont. K 144 Continued From page 1 K 144 1/21/11 the annuniciator panel will be installed by January 21, 2011. 3 After the annunciator panel is installed, we will inspect it weekly for four (4) weeks, then monthly to ensure it is functioning properly. This STANDARD is not met as evidenced by: 4 The results of the inspections Based on observation and interview, the facility will be reported to the Quality failed to assure the emergency generator was Assurance committee at the provided with a remote annunciator in a monthly meeting until which time continuously occupied area. (NFPA 99, it is deemed to be functioning -4.1.1.15). at it's expected level. The findings include: Observation and interview with the Maintenance Director, on December 5, 2010 at 11:30 a.m., confirmed the emergency generator was not provided with a remote annunciator in the building.